

YR	MO	DY		sample location	on site/ CCl lab	Results
			analyte			
2004	7	8	TKN	Effluent	CCl Lab	1.200
2004	7	28	TKN	Effluent	CCl Lab	1.000
2004	9	2	TKN	Effluent	CCl Lab	0.980
2004	9	16	TKN	Effluent	CCl Lab	0.860
2004	10	13	TKN	Effluent	CCl Lab	0.740
2004	11	23	TKN	Effluent	CCl Lab	0.610
2005	1	20	TKN	Effluent	CCl Lab	0.092
2005	2	11	TKN	Effluent	CCl Lab	1.100
2005	2	25	TKN	Effluent	CCl Lab	1.100
2005	3	4	TKN	Effluent	CCl Lab	1.300
2005	4	26	TKN	Effluent	CCl Lab	1.400
2005	5	5	TKN	Effluent	CCl Lab	1.300
2005	6	9	TKN	Effluent	CCl Lab	1.600
2005	6	29	TKN	Effluent	CCl Lab	1.300
2005	10	12	TKN	Effluent	CCl Lab	2.200
2006	1	25	TKN	Effluent	CCl Lab	8.300
2006	1	31	TKN	Effluent	CCl Lab	6.300
2006	2	7	TKN	Effluent	CCl Lab	1.800
2006	2	22	TKN	Effluent	CCl Lab	7.000
Average						2.115
Maximum						8.300
Minimum						0.092

